



GARY R. HERBERT Governor SPENCER J. COX Lieutenant Governor

## State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER Executive Director JOHN R. BAZA Division Director


## INSPECTION REPORT

## MINERALS REGULATORY PROGRAM

REPORT DATE: MAY 7, 2019

Mine Name: Asphalt Ridge 2	Inspection Date: 05/07/2019 10:32 AM
Permit Number: M/47/0032	Inspection Time: 11:00 AM
Mine Status: Active	Inspector(s): April Abate
Operator Name: Tar Sands Holdings II	Prior Inspection: Jun 28, 2017
Attendee(s): A. Burrows, D. Hall, W. Campbell, . Novak, Div. Water Quality	Permit Fees: Paid
Weather: Sunny/Overcast	Bond Amount: \$792,000
Reviewed By:	Bond Escalation: Mar 2, 2016
Inspection Purpose: Routine inspection	

Conclusions and Recommendations: Site needs additional maintenance work on the seeps. Operator committed to maintenance on seeps by covering them with large boulders and to remediate leak from processs tank.



Coordinates: Latitude: 40.43450, Longitude: -109.59558

2. Public Safety (shafts, adits, trash, signs, highwalls)

## ELEMENTS OF INSPECTION

1. Permits, Revisions, Transfer, Bonds

☐: Evaluated
☐: Enforced

Comment: Company has provided samples from mine reserves to potential investors and to asphalt manufacturers. This is what supposedly has comprised the 1600 tons from 3 stockpiles reported in the 2018 Annual report submission.

2. Public Sector (classical description of the public leading to the public lea

Comment: Scrap metal, salvaged equipment, crates and drums containing bitumen remain on the site in the boneyard areas.

Should be cleaned up and taken offsite for proper disposal if no future use is planned.

3. Protection of Drainages/Erosion Control


x: Evaluated

Comment: Vivakor is no longer operating on the site. Another group is conducting due dilligence on purchasing the property.

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801 Telephone (801) 538-5340 Fax (801) 359-3940 TTY (801) 538-7458 www.ogm.utah.gov



DWQ granted old permit-by-rule on the condition that they will that flows into the main pit showed heavy oxidation flowing ove areas with gravel to limit the surface exposure and minimize acid	
4. Deleterious Material	x : Evaluated
Comment: Small leak on one tank. Could not determine based or mixurebof both. Operator acknowleged it and will look into rem	
5. Roads (maintenance, surfacing, dust control, safety)	x : Evaluated □ : Enforced
Comment: Water bars installed for storwater diversion are in good	od working order.
6. Reclamation	x : Evaluated □ : Enforced
Comment: No reclamation is occurring on the site. Boneyard are almost new/barely used.	eas contain lots of scrap metal and equipment that appers to be
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts)	x : Evaluated  □ : Enforced
Comment: No backfilling or grading is occurring at the present time.	
8. Soils	□ : Evaluated □ : Enforced
Comment:	
9. Revegetation	□ : Evaluated □ : Enforced
Comment:	
10. Other	□ : Evaluated □ : Enforced
Comment:	




Longitude: -109.59831
Latitude: 40.43629
Comment: Minor leak was oberved from one of the process tanks (approx. 1-2 gallons), below reportable qty




Longitude: -109.59550 Latitude: 40.43453 Comment: Entry sign



Longitude: -109.60018
Latitude: 40.43325
Comment: Example of active seep. Drains into mine pit. No offsite impact.



Longitude: -109.60055
Latitude: 40.43364
Comment: Stormwater was present in and near the main mine pit.



Longitude: -109.60039
Latitude: 40.43402
Comment: Bitumen product containers located on the property.

INSPECTOR'S SIGNATURE

SUGGESTIONS/EDITS:

Reviewer:

File:

cc. Brent andrewsen, bandrewsen@kmlaw.com Devise Dragoo, ddragoo@swlaw.com

